


Figure 5:
Humidity/Fan Control Panel
Part No. 4024155



Do not connect these leads directly together or damage to the transformer will result.



Figure 6: Ventilation Timer
and Humidity Control Panel
Part No. 4024125

